

0 1.25 2.5 5 Miles





**RECLAMATION**  
Managing Water in the West

# Reach 3 Temperature Monitoring



Preliminary Data

### Temperature SJRMP



### San Joaquin River Restoration Program

Reach 3                      Bank = Right  
 River Mile = 204.5  
 Site = Mendota Pool

Latitude (NAD83) = 36.792138  
 Longitude (NAD83) = -120.371179

Status = Existing  
 Depth = 1 ft above gs

Hour    Datalogger  
 Habitat = glide  
 Organization = DFG


Most Recent Meas. = 11/30/2010

Description:  
 Downstream of Mendota Pool. Cabled to tree on RR.

gs = ground surface  
 ws = water surface

Preliminary Data

— Hourly temperature (C)  
 — Daily average temperature (C)



# Temperature Monitoring SJRMP

